


Mounting facilities of the end pieces


Horizontal

with screws for thread d₄ or bore d₅




Vertical


From outside, with screws for thread d_3 From inside, with screws for bore d_6 From inside, with screws for bore d_5 / d_7



Mounting facilities at the slider

Mounting with screws for thread d4 or bore d5





Assembly of position indicator and handwheel

Usage of installation kit, position indicator and handwheel, see table \rightarrow Page 1996

